

MOTOR DATA SHEET

Motor type: **Sh450H6A**

Series: **HIGH EFFICIENCY**



14-06-2025

| | ELECTRICAL PARAMETERS | | | | | | | | | | | | | | | | |
|------|-----------------------|----|-----|-----|------|------|-----|------|------|------|------|--------|-------------|-------|-------|---------------|---------|
| U | CONN. | f | ŀ | • | Duty | 1 | n | Т | TL/T | TB/T | IL/I | Effici | ency at loa | d [%] | Power | r factor at l | oad [-] |
| V | - | Hz | kW | HP | - | Α | rpm | Nm | - | - | - | 2/4 | 3/4 | 4/4 | 2/4 | 3/4 | 4/4 |
| 6000 | Y | 50 | 450 | 600 | S1 | 53.7 | 992 | 4332 | 0.8 | 2.2 | 5.2 | - | - | 96.0 | - | - | 0.84 |

| GENERAL DATA | | | | | | |
|----------------------------|------------|--------------------------------------|--------------------|--|--|--|
| Efficiency class | - | Sound pressure level [dB] | 81 | | | |
| Frame size | 450 | Sound power level [dB] | - | | | |
| Number of poles | 6 | Terminal box position | top/ * side | | | |
| Starting method | DOL | Possibility of terminal box rotation | yes | | | |
| Insulation class | F | Bearing on D-side | 6324MC3 | | | |
| Frequency converter supply | on demand | Bearing on ND-side | NU222EM1/*7322BTVP | | | |
| Mounting arrangement | B3/B35/V1* | Bearings regreasing | yes | | | |
| Cooling method | IC411 | Housing - material | cast iron | | | |
| Weight (IMB3) [kg] | 3800 | Feet - material | cast iron | | | |
| Moment of inertia [kgm2] | 25.3 | Bearing shields - material | cast iron | | | |
| Direction of rotation | CW/CCW | Painting | RAL5010 | | | |
| Degree of protection | IP55 | Climatic execution | N | | | |

| ENVIRONMENTAL CONDITIONS | | | | | | | |
|--------------------------|---|--|------------|--|--|--|--|
| Ambient temperature [°C] | from -20 up to +40 Altitude above sea level [m] | | up to 1000 | | | | |
| Relative humidity [%] | up to 95 | | | | | | |

| ACCESSORY | | | | | | | |
|--------------------------------|--------------------------|---------------------------------|--------------------------|--|--|--|--|
| Number of terminals or cables | 3 | Temperature sensors in bearings | 2 x Pt100 (1 pc/bearing) | | | | |
| Cable glands/inlets | 1 | Winding heaters | on demand | | | | |
| Temperature sensors in winding | 6 x Pt100 (2 pcs./phase) | Optional accessories | on demand | | | | |

| STANDARDS |
|-------------|
| IEC 60034-1 |

| CERTIFICATES | | | | | |
|--------------|--|--|--|--|--|
| on demand | | | | | |

